


The most important safety rules at the Würzburg site (as of 24.01.2025)



Please read the safety rules before entering our location and be aware of them during your stay!

As a general rule, no work without a risk assessment / permit!



Always authorize work with the permission slip

Pay attention to cleanliness

In the event of a medical emergency, accident, fire, pollution, traffic accident or damage caused by other hazards, you must call the works emergency number immediately. Please save the emergency number on your mobile phone before your call.



112 Emergency number (fire, accident, rescue service) **0931/9084-222** (works emergency call) Other important telephone numbers:

0931/9084-251 First aid station Occupational health and safety	0931/9084-218 0931/9084-295	Plant security Tor1 company fire brigade	0931/9084-385 Responsible Care Mobile 0173/3798956
---	--------------------------------	---	---

Important information for the emergency call:



where happened?
what how Happened?
many Injured? Injury?
which are Questions?
waiting



Bring people to safety Warn helpless people



In the event of an alarm, the assembly point assigned to the Würzburg location must be visited immediately and the completeness must be determined. Rescuing people takes precedence over firefighting!



CO² extinguishing areas are marked by yellow signs at the entrances. These areas are protected by an automatic extinguishing device for firefighting.

When the horn sounds, the building must be left immediately and the collection point must be visited. There is an acute danger to life!

After the warning time (30 seconds) has elapsed, the doors and windows close automatically. The doors can still be opened by hand at any time. Inhalation of increased carbon dioxide concentrations leads to suffocation after a very short time. Work in which it is not guaranteed that the rooms will be left within the warning time, e.g. driving on containers, work on scaffolding, lifting equipment, etc., may only be started when the automatic CO² extinguishing has been taken out of operation by the company fire brigade. The documentation is done in the permit certificate. Emergency exit doors, escape routes, stairs, other entrances/exits must not be blocked or their automatic closure may be overridden.



The most important safety rules at the Würzburg site (as of 24.01.2025)



Hazardous substances with the GHS symbols shown are handled at the site. The protective measures are listed in the associated safety data sheets and must be observed.



In a chemical plant, personal hygiene of employees is of paramount importance. Eating and drinking is only allowed in the designated rooms. Soiled work clothes must be changed in good time. Clothing that has come into contact with chemicals must be changed immediately.

Leakage damage and other environmental damage must be reported immediately to the company fire brigade (emergency 0931/9084-222, otherwise Tel. 0931/9084-218). The spread of damage must be limited by suitable measures (e.g. covering drains).



The appropriate protective equipment must be worn in the marked work areas.



Ex areas may only be entered with safety shoes with antistatic soles (at least EN 345 S1). Visitors are also allowed to wear sturdy shoes with electrostatic leakage strips. The function of the drainage strip must be tested with a test device. In hazardous areas, it is generally prohibited to carry or use devices that can become a source of ignition, e.g. mobile phones, non-explosion-proof motor vehicles, transport vehicles, tools, walkie-talkies, flashlights, small appliances such as calculators, lighters, matches, etc. A permit is required for work in hazardous areas.



Warning of Explosive Atmosphere

Ex areas are marked by yellow signs at the entrances (Explosive Atmosphere Warning) Additional regulations and rules of conduct must be observed.

Vertical ladders: The use of vertical ladders as an ascent is only permitted at the entire site with an existing order and a risk assessment/permit certificate.



Maximum speed on the factory premises is 20km/h, park vehicles in marked parking areas and must not block access to safety equipment!



Warning of Industrial trucks

Traffic of industrial trucks on the entire factory premises



Absolute smoking ban on the entire factory premises including vehicles.



Hazards from magnetic and electromagnetic fields cannot be ruled out. Persons with influenceable body aids must report in advance.



The operation and starting of machines, systems and switches is prohibited.



The transport, storage and consumption of food and beverages is prohibited in areas with open chemical handling.



Working at height always with Fall protection



Removing and bypassing Safety forbidden



No access for people with pacemakers. (Specially marked areas)



Photography ban at the entire site (only possible with special permission).



Entering marked areas Hazardous areas prohibited



Electrical devices such as laptops or mobile phones are prohibited in designated areas. The only exception: specially approved devices in Ex design.



Absolute ban on alcohol and drugs on the entire factory premises.



Animals are prohibited.